



Petroleum Services
6316 Windfern
Houston, Texas 77040 USA
Tel: 713-328-2565
Fax: 713-328-2567
www.corelab.com

UltraScanSM

CT Scan Report

for

Denbury Resources, Inc.
Bell Creek 33-14R

December 19, 2013
HOU-13060



Denbury Resources, Inc.

Bell Creek 33-14R

File No.: HOU-130630

Date: December 19, 2013

0°

90°




Axial

Depth: (ft)

4426.40

Plug No.:

1T




Depth: (ft)

4433.10

Plug No.:

2T





Denbury Resources, Inc.

Bell Creek 33-14R

File No.: HOU-130630

Date: December 19, 2013

0°

90°




Axial

Depth: (ft)

4434.50

Plug No.:

3TH






Depth: (ft)

4434.70

Plug No.:

3TV





Denbury Resources, Inc.

Bell Creek 33-14R

File No.: HOU-130630

Date: December 19, 2013

0°

90°



Axial

Depth: (ft)

4445.10

Plug No.:

4T






Depth: (ft)

4454.00

Plug No.:

5T



UltraScan™